

Playground Routine Visual Inspection

Playground Routine Visual Inspection

Complete

Score	20 / 25 (80%)	Flagged items	4	Actions	0
Site:	Grace's Playground, Ilmington				
Conducted on:	29.08.2026 17:54 BST				
Report prepared by:	Pauline Rigby				
					000099

Flagged items

4 flagged

Questions / Playground equipment

5. Junior swings

Defect

Swing seat missing a nut, detached on one corner. Taken out of action.



Photo 1



Photo 2

Questions / Playground equipment

9. Adventure trail

Defect

Questions / Playground equipment

19. Wooden slide unit

Defect

Questions / Playground equipment

20. MUGA

Defect

Questions		4 flagged, 20 / 25 (80%)
Playground equipment		14 / 18 (77.78%)
1. Rocking horse		No defect
2. Embankment slide		No defect
3. Parallel bars		No defect
4. Basket swing		No defect
5. Junior swings		Defect
Swing seat missing a nut, detached on one corner. Taken out of action.		
  Photo 1 Photo 2		
6. Carousel - Supernova		No defect
7. Hanging bars		No defect
8. Multi-play unit with tube slide		No defect
9. Adventure trail		Defect
10. Log climber		No defect
11. Sand pit		No defect
12. Musical activities x 3		No defect
15. Cradle swing		No defect
16. Playhouse		No defect
17. Springers x 2		No defect
18. Small multi-play unit		No defect
19. Wooden slide unit		Defect
20. MUGA		Defect
Ancillary equipment		6 / 7 (85.71%)

Gates: Are the gates functioning correctly?	Yes
Litter bins: Have they been emptied?	Yes
Is the playground free from vandalism, broken glass, graffiti?	Yes
Benches: Are they sturdy and in good condition?	Yes
Picnic tables: Are they sturdy and in good condition?	Yes
Surfacing: Are the surroundings free of notable trip hazards?	No
Cracking issues as before	
Drainage: Is the ground well drained and free from pooling water?	Yes
General observations:	
Add any other comments here:	
No wasps, nest is gone, removed warning tape and slabs	

Media summary



Photo 1



Photo 2